

Anchor Reset Tests

The Fortress reset best, simply swiveling and re-aligning itself. The Bulwagga and the Spade performed admirably, too. The Hans C-Anchor and Hydro-Dyne failed to reset.

A properly set anchor should stay put during lunch, while you're sleeping or when the wind and waves whip up. It should also keep the boat safe while unattended.

But what happens when you're not aboard and the wind or current sharply changes direction? The well-set anchor must somehow re-align itself to the new heading and reset. This scenario raises two questions:

1. Does the anchor, without losing much of its grip, simply swivel in the mud or sand and steady up?
2. Or does the anchor pull free, flip on its back or roll up on edge and then reset itself?

Seeking answers to these questions produced some dramatic results for this latest report in our continuing series on the in-water performance of about two dozens makes and types of anchors. Here's a summary of our three previous reports:

- In the February 1998 issue, we concluded that the Bulwagga, Spade and Bruce were the best of 11 anchors at setting in the sand.
- In the January 1999 issue, we tested 15 anchors for holding power in sand. The Spade, Bulwagga and CQR rated best.
- In the December 1999 issue, we wanted to find out which of 17 anchors set and held best in mud. Tops for setting was the Delta; six anchors tied for second. For holding power, the top three were the Barnacle, CQR and Bulwagga.

At the end of those three sessions, we concluded that the top three anchors for sand and mud holding power were the Spade, Bulwagga and CQR.

We think you should read these three reports, which contain valuable information about how anchors behave in different settings, in addition to this one, before selecting an anchor.

Consider, for instance, this finding. While setting anchors with an electric winch and measuring the load on a dynamometer, it was noted that even moderate readings on the dynamometer immediately started down when the hauling ceased. This indicates clearly that the anchor is moving ... minutely, of course, but if subjected to some tugging in a roily harbor, the minute creeping can become dragging.

For even more complete coverage of this important subject, take a look at our reports on anchor rode loads, swivel shackles, chain tests, rope/chain splices, sentinels and bow rollers. In addition, we've done tests on the many makes of rope anchor rode, and a two-part report on anchor windlasses.

What We Tested

We started out several summers ago with 11 anchors.. However that number did not remain constant over the ensuing tests.

An anchor that simply would not set, even in sand, was dropped from subsequent tests, as was a box-like



Above: One of our testers indicates with his right hand the distance traveled by the Spade anchor when the rode lead was changed. In his left hand is a fiberglass stick used to mark the original position. The Spade anchor, which has a yellow face, appears to be out of the water, but is submerged. The anchor and the two rodes indicate how easy it was to closely observe the anchors.

folding anchor really meant for a small boat.

Two other anchors, which were attempts to improve on established designs, proved not as good and were retrieved by their inventors—one a co-owner of one of the world's most successful anchor manufacturers.

Meanwhile, other new or lesser-known anchors were submitted by their creators, including three that strongly challenge established favorites: The Barnacle, the Bulwagga and the Spade.

One truth emerges: Be assured that as you read this there are some very ingenious, recusant individuals working diligently to produce an anchor that "does it all." And it may



Above: Left to right, the Danforth, Fortress, Nautical Engineering, Vetus and West Marine Performance² are remarkably similar in appearance and performance, except for the NE, which has too short a stock.

Above: Shown here are several 'old reliables,' plus the French-made Spade. From left to right are the CQR, Delta, Spade and two versions of the Supermax, one with a fixed shank, the other adjustable for different type bottoms.

happen, much to the benefit of all boaters.

In fact, for this phase of the testing we have three new anchors, which means that, as before, prior tests in sand and mud must be duplicated to obtain comparable data. The three new anchors are the Herreshoff Bronze, the Hydro-Dyne and the Seagrip.

In all cases, the size of anchor selected for the tests was determined by asking each manufacturer for the anchor they recommend for a 30'-32' boat anchored in up to 42 knots of wind in sheltered water. (For test purposes, an anchor is considered set when it withstands a 200-lb. load; an anchor meets the above criteria when it withstands a 400-lb. load.)

The 18 anchors in this round are the 25-lb. Barnacle, the 22-lb. Bruce, the 17-lb. Bulwagga, the 22-lb. Claw, the 35-lb. CQR, the 20-lb. Danforth Deepset II, the 22-lb. Delta, the 10-lb. Fortress FX-16, the 15-lb. Hans C-Anchor, the 17-lb. Herreshoff Bronze, the 10-lb. Hydro-Dyne, the 20-lb. Nautical Engineering, the 33-lb. Seagrip, the 26-lb. Supermax Adjustable, the 26-lb. Supermax, the 16.5-lb. Spade, the 12-lb. Vetus and the 25-lb. West Marine Performance². (We tried unsuccessfully to obtain for testing a German anchor called a Bugel, about which several readers have inquired.)

The 18 anchors in hand defy categorization by type, but an attempt is made in the photos to group the lightweight, twin-fluke types, those resembling a plow and those that fit neither category. The three new anchors—the Herreshoff Bronze, the Hydro-Dyne and the Seagrip—are shown in separate photos.

How We Tested

We test the anchors in shallow water, which empowers us with very pre-

cise control of the all-important scope, but even more importantly permits a test member to observe each anchor's behavior. The hauling and measuring equipment is securely mounted ashore—on seawalls, docks or other solid bases.

The objective in this test was first to set each anchor in sand. The rode then was relaxed.

A load then was applied to a second rode led back about 140° to 150° off the original rode's line. The scope was held between 7:1 and 6:1.

We opted against pulling at 90° because we'd likely roll the anchors sideways. We also decided against leading back at exactly 180° because it might induce the anchors into a back flip. Most prone to back flips are the twin-point lightweight anchors because of their inherently balanced distribution of weight.

As it turned out, experimenting with different angles revealed no surprises, neither did laying an anchor with an unbalanced or hinged shank (like the Barnacle and CQR) on one edge or the other. And several experiments with the lightweight anchors produced the back flipping mentioned above (see photo on Page 26).

As a load was applied to the second rode, the observer in the water carefully noted how each anchor realigned itself by swiveling, rolling or flopping on its backside. Of par-



Left: The Barnacle, shown at the left, is an unusual one-fluke anchor that stows flat. At the right is the Bulwagga anchor that challenges the Spade in every category. The Bulwagga's only shortcoming: It's clumsy to handle and difficult to stow.

Value Guide: Anchors

Name	Weight	Setting Rank			Holding Power				Average	
		Sand	Mud	Combined	Sand	Rank	Mud	Rank	Holding	Rank
Barnacle	25 lbs.	16	9 Tie	12 Tie	355 lbs.	9	800 lbs.	1	577 lbs.	4
Bruce	22 lbs.	3	2 Tie	1	307 lbs.	11	550 lbs.	8	429 lbs.	10
Bulwagga	17 lbs.	1	8	4 Tie	816 lbs.	2	680 lbs.	3	748 lbs.	2
Claw	22 lbs.	8	2 Tie	4 Tie	283 lbs.	14	520 lbs.	9	401 lbs.	12
CQR	35 lbs.	15	2 Tie	9	583 lbs.	3	760 lbs.	2	672 lbs.	3
Danforth Deepset II	20 lbs.	14	15	14	363 lbs.	8	640 lbs.	5	502 lbs.	6
Delta	22 lbs.	13	1	7	496 lbs.	4	610 lbs.	6	553 lbs.	5
Fortress FX-16	10 lbs.	9	13	11	471 lbs.	5	420 lbs.	12	446 lbs.	8
Hans C-Anchor	15 lbs.	17	12	15	0 lbs.	17	350 lbs.	15	175 lbs.	15
Herreshoff Bronze	17 lbs.	6	—	—	300 lbs.	12	—	—	—	—
Hydro-Dyne	10 lbs.	Failed	—	—	—	—	—	—	—	—
Nautical Engineering	20 lbs.	11	14	12 Tie	235 lbs.	15	390 lbs.	14	313 lbs.	14
Seagrip	33 lbs.	12	—	—	200 lbs.	16	—	—	—	—
Supermax (Adj. shank)	26 lbs.	7	2 Tie	3	410 lbs.	7	430 lbs.	11	420 lbs.	11
Supermax	26 lbs.	5	2 Tie	2	350 lbs.	10	400 lbs.	13	375 lbs.	13
Spade Model 80	16.5 lbs.	2	7	6	1,000 lbs.	1	660 lbs.	4	830 lbs.	1
Vetus	12 lbs.	4	9 Tie	8	285 lbs.	13	590 lbs.	7	438 lbs.	9
West Performance ²	25 lbs.	10	11	10	456 lbs.	6	460 lbs.	10	458 lbs.	7

ticular interest was whether the anchor broke out completely or retained some or all of its grip while rotating horizontally in the sand. Then the distance from the “old set” to the “new set” was measured.

The rodes were a 250' continuous piece of 1/2" Samson Super

Strong nylon double braid. Hauling was done with a Harken 32 self-tailing winch. The blocks used were Lewmar and Schaefer ball-bearing models, and the load measurements were done with a calibrated Dillon dynamometer with a very handy “max” needle.

der constant visual observation. Each was pulled at least once, more if anything unusual was observed, such as a long distance to reset.

When the 140° resets were completed, we tried one lightweight anchor at 180°. After resetting the West Marine Performance², the rode was reversed 180°. When the load was applied, the anchor backed straight out of the sand until, when about half out, the shank lifted up and over and, as one would expect, the anchor flipped on its back. It refused, however, to reset, even when pulled a considerable dis-

The Results

The sandy bottom where we tested the anchors appeared very even; the anchors were un-



Left: The circular plastic float material clamped in the back of the shank is supposed to assure that the Hydro-Dyne anchor settles upright on the bottom then engages the bottom with the stainless steel plow. We could not get the anchor, when dropped in the water, to assume the proper position. This anchor retails for \$165.

Reset Results In Sand

Name	What Happened	How Far Moved Before Reset
Barnacle	Swiveled in flat plane (tried on both sides)	1' 6"
Bruce	Rotated horizontally, with little movement	4"
Bulwagga	Balanced on 2 flukes, fell over, took hold	2'
Claw	Swiveled up and out, then reset	2'
CQR	Rolled out on hinged arm but dug back in	9'
Danforth Deepset II	Did not break out flukes, stayed buried	1'
Delta	Rolled on side, came loose and dug back in	5'
Fortress FX-16	Swiveled very flat, crown moved very little	6"
Hans C-Anchor	Swiveled but then dragged	No set
Herreshoff Bronze	Rolled out, but stock forced other fluke in	3'
Hydro-Dyne	Dragged on its side	No set
Nautical Engineering	Rolled, flopped, short stock finally grabbed	14'
Seagrip	Swiveled, pulled out and reset	7'
Supermax (Adj. shank)	Turned in horizontal plane, moved very little	0' 0"
Supermax	Rolled out, flipped on back, dragged on side	4'
Spade Model 80	Aligned to new pull with little movement	0' 0"
Vetus	Rolled out, tripped on stock, flattened, reset	8'
West Performance ²	Rolled up 45°, pivoted on 1 fluke, flattened	2'

The anchors that broke free and did not reset but merely skipped or slid along the sandy bottom were the Hans C-Anchor and the Hydro-Dyne.

The remainder of the anchors in the other three groups either did not break out or did reset themselves.

The group that broke out and dragged 3 or more feet before resetting and holding 200 lbs. included the CQR, the Delta, the Nautical Engineering, the Seagrip, the Supermax and the Vetus.

Better test results—meaning that the anchors either didn't break out completely or that they reset very quickly between 6" and 3"—were the Barnacle, the Claw, the Bulwagga, the Danforth Deepset, the Herreshoff Bronze and the West Marine Performance².

In the best test group, those that did not break out and moved very little (from not measurable to no more than 6"), were the Bruce, the Fortress FX-16, the Supermax (with the adjustable shank) and the Spade.

The behavior of each anchor is

tance. It then was noted that the flukes were not pointed down. When lifted from the water, the observer found a clam stuck in the angle between a fluke and the shank! Though unlikely, this is a possible scenario for any lightweight-type anchor. Not only shellfish can cause the flukes to jam, but also a piece of wood or rock.

Once again, we were reminded that seemingly minute variations in the bottom can produce magnified

differences in how an anchor sets. Therefore, the chart data showing how far each anchor was pulled before setting and satisfying the 200-lb. pull requirement should not be regarded as a precise number that will be true in all situations.

Instead of ranking the anchors, we placed them in four groups. The groups, from the poorest to the best, are those that broke free and failed to reset, those that reset in 3' or more,

those that reset in 6" to 3' and those that moved less than 6" while swiveling into the new position.



Left: This 1914 Herreshoff design, once the world's most popular anchor, has been out-done by more modern anchor but is still favored as a 'rock' anchor. This Herreshoff, which retails for \$375, sets quickly. It did well in this reset test. Its weakness is holding power. **Above:** The Herreshoff folds for stowage. There is a smaller size whose threaded shank makes an even smaller package to stow.





Left: New in the US, the unusual Seagrip was invented by a pair of Swedish fishermen. Acting somewhat like a propeller, the Seagrip is supposed to screw itself into the bottom (we assume greater loads than we developed would be required for this action to occur). In sand, it set in less than 3' but developed only 240 lbs. of holding power. **Right:** The Seagrip (\$325) is shown folded.



noted in the comments column of the chart on this page.

Would the same results prevail in mud or a gravel bottom? The answers must await other rounds of this continuing series of tests.

The Bottom Line

Although minute differences might not seem important when considering an anchor's ability to withstand a pull in a new direction, those that did not break out surely are preferable to those that broke out, moved and re-set. An anchor that must reset itself represents a danger—partly because the bottom might change, debris can be picked up or the rode can foul the anchor.

The Herreshoff Bronze was a surprise. This handsome new version of a traditional anchor set quickly in 2', and broke out and reset itself in 3'. In sand, its weak point is holding. It dragged at 300 lbs., 100 lbs. short of the 400-lb. requirement. It is essentially a rock anchor.

The best lightweight anchor was the Fortress, which simply swiveled in a horizontal plane around the shank and took up its new alignment. In the setting and holding tests, the Fortress ranked near the middle. The performance of the Bruce was no surprise, considering it ranked near the top for setting (in either sand or mud). Because of its mediocre holding power, we recommend selecting a larger size Bruce. The same is true of the Supermax. The Bulwagga and the

Spade performed in a manner that did nothing but enhance the showings they made in the sand/mud setting and holding phases. ■

Contacts—Barnacle, 1020 24th Ave. E., Ellenton, FL 34222; 800/295-2766.

Bruce, Bruce/Imtra, 30 Barnet Blvd., New Bedford, MA 02745; 508/995-7000.

Bulwagga, NoTECO, Inc., Box 533, White Church Rd., Crown Point, NY 12928; 888/674-4465. **CQR, Delta & Claw**, Lewmar, 351 New Whitfield St., Guilford, CT 06437; 203/458-6300. **Dan-**

forth, Rule Industries, Cape Ann Industrial Park, Gloucester, MA 01930; 978/281-0440. **Fortress**, 1386 W. McNab, Ft. Lauderdale, FL 33309; 800/825-6289. **Hans C-An-**

chor, Box 66756, St. Petersburg, FL 33736; 800/728-4645. **Her-**

reshoff Bronze, J.M. Reineck & Son, 9 Willow St., Hull, MA 02045-1121; 781/925-3312. **Hydro-**

Dyne, 1424 Old U.S. 264, Zebulon, NC 27597; 919/404-0409. **Nautical En-**

gineering, 700

Doheny Dr., Northville, MI 48167; 248/349-1034. **Seagrip**, 511 Sunset Beach, Richmond Hill, Ontario, Canada, L4E-3J7; 905/773-4002. **Spade**, B.P. 103-40, rue Ibn Safouane, 2036 La Soukra, Tunisia; 216/1 869 099; fax 216/1 865 250. **Supermax**, Box 2120, 243 John R. Junkin Dr., Natchez, MS 39121-2120; 800/824-0355. **Vetus**, Vetus Den Ouden Inc., Box 8712, Baltimore, MD 21240; 410/712-0740. **West Performance**, West Marine, 500 Westridge, Watsonville, CA 95077-5050; 800/538-0775.



Above: On the 180° reverse set with the West Performance², the anchor backed halfway out, flipped on its back and refused to reset. When plucked from the water, a clam was found neatly wedged between the flukes and the shank. This can be a problem with any anchor.